



# Butler SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Cover and Green Manure Crop	795.3		
Residue & Tillage Mgt.- Mulch Till	88.2		
Brush Management	16.0		
Wetland Enhancement	2.0		
Subsurface Drain		28,374	
Grassed Waterway		15,237	
Stream Restoration/Enhancement		1,330	
Natural Resource Review			62
Technical Assistance - Drainage			32
Grade Stabilization Structure			19
Technical Assistance - Streams			13
Pond Management			13
Urban - Plan Review			7
Pond Site Investigation			6
Floating Treatment Wetland			6
Technical Assistance - General			5
Erosion - I & E (Inventory & Evaluation)			2
Complaint Investigation/Resolution - Livestock			1
Conservation Easement Inspection			1
I & E (Inventory and Evaluation)			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Champaign SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Subsurface Drain		18,022	
Grassed Waterway		14,171	
Erosion Control Structure			4
Blind Inlet			3
Stone Center Outlet			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Clark SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Rural - Property Evaluation	271.0		
Topographic Survey	174.0		
Tree/Shrub Establishment	15.0		
Pest Management	1.0		
Pond	0.3		
Subsurface Drain		58,565	
Grassed Waterway		6,019	
Drainage - Two-Sided Construction		5,000	
Surface Drainage, Field Ditch		3,500	
Diversion		1,000	
Streambank and Shoreline Protection		30	
Technical Assistance - Drainage			16
I & E (Inventory and Evaluation)			14
Pond Site Investigation			8
Grade Stabilization Structure			7
Pond Management			7
Tile Plan Developed			3
Erosion - I & E (Inventory & Evaluation)			3
Technical Assistance - Streams			2
Stream Crossing			1
CRP - MCM Assessment/Review			1
Seasonal High Tunnel System for Crops			1
Soils - General Assistance			1
Septic System Repair			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Clinton SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Grassed Waterway		11,050	
Erosion Control Structure			19
Stone Center Outlet			13
Soils - General Assistance			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Clermont SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Heavy Use Area Protection	0.3		
Heavy use protection pad constructed w/ stone & geo-textile fabric	0.1		
Pipeline		1,641	
Subsurface Drain		1,052	
Grassed Waterway		455	
Access Road		400	
Technical Assistance - Drainage			62
Pond Management			19
Technical Assistance - General			16
Pond Site Investigation			12
Technical Assistance - Silviculture			8
Urban - Rain Garden			7
Soil Quality Analysis			4
I & E (Inventory and Evaluation)			3
Watering Facility			3
Technical Assistance - Streams			2
Erosion - I & E (Inventory & Evaluation)			2
Structure for Water Control			2
Pond Management			1
Stream Crossing			1
Pumping Plant			1
Complaint Investigation/Resolution - Silviculture			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Darke SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Conservation Crop Rotation	3,704.7		
Residue Management, No - Till and Strip Till	3,694.7		
Soil Testing, General - <25 ac/sample	2,400.0		
Settling basin	80.0		
Filter Strips	26.9		
Cover and Green Manure Crop	18.5		
Windbreak/Shelterbelt Establishment - Acres	1.3		
Grassed Waterway		60,668	
Subsurface Drain		5,172	
Complaint Investigation/Resolution - Livestock			15
APA - Site Visit			13
I & E (Inventory and Evaluation)			10
Soil Quality Analysis			6
Soils - General Assistance			4
Monitoring / Sampling			4
Natural Resource Review			3
Wildlife Damage Investigation - Deer			2
Wildlife Habitat Assistance			2
Gutters and / or roofing			1
Waste Storage Facility			1
Animal waste storage structure (AWSS) - exclude rainwater with a roof			1
Dry Stack or semi-solid manure storage - no roof			1
Wildlife Damage - Raccoon			1
Nuisance Animal Complaint			1
Grade Stabilization Structure			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Fayette SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Conservation Crop Rotation	2,423.6		
Residue Management, No - Till and Strip Till	1,595.9		
Drainage - Acres in Drainage Area	1,100.0		
Residue & Tillage Mgt.- Mulch Till	827.7		
Conservation Cover	219.2		
CNMP	10.2		
Field Border	4.2		
Early Successional Habitat Development/management	2.6		
Filter Strips	2.5		
Prescribed Grazing	2.2		
Pasture and Hayland Planting	2.2		
Critical Area Planting	0.7		
Wetland Restoration	0.4		
Heavy Use Area Protection	0.1		
Subsurface Drain		7,241	
Grassed Waterway		6,845	
Open Channel		4,950	
Drainage - Tile Main		2,367	
Dike		350	
Lined Waterway or Outlet		93	
Erosion - I & E (Inventory & Evaluation)			339
I & E (Inventory and Evaluation)			237
Pond Site Investigation			20
Technical Assistance - Drainage			14
Technical Assistance - General			12
Seasonal High Tunnel System for Crops			6
Structure for Water Control			4
Erosion Control Structure			1
Underground Outlet			1
Stone Center Outlet			1
Roof Runoff Structure			1



Conservation Districts



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Greene SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Subsurface Drain		254,187	
Grassed Waterway		12,483	
Urban - Sediment & Erosion Control Inspection			238
Urban - Site Inspection			131
Urban - Plan Review			70
Pond Site Investigation			41
DM - Annual Maintenance Completed			33
Stone Center Outlet			5
Grade Stabilization Structure			3



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Hamilton SWCD

## 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Cover and Green Manure Crop	97.3		
Pasture and Hayland Planting	7.1		
Forest Stand Improvement	2.5		
Heavy Use Area Protection	0.2		
Fence		2,100	
Access Road		65	
Urban - Sediment & Erosion Control Inspection			2,506
Urban - Plan Review			1,286
Urban - Technical Visit			685
Spring Development			1
Watering Facility			1
Roof Runoff Structure			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Logan SWCD 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Wetland Restoration	90.0		
Heavy Use Area Protection	0.0		
Grassed Waterway		26,995	
Subsurface Drain		5,550	
Grade Stabilization Structure			3
Blind Inlet			2
Complaint Investigation/Resolution - Livestock			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Madison SWCD 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Agricultural Easement Installation	452.0		
Conservation Plan	179.0		
Grassed Waterway		37,464	
I & E (Inventory and Evaluation)			4
Urban - Water Quality Feature Inspection			2
Pond Site Investigation			2
Pond Management			1
Technical Assistance - Streams			1
Site Meeting / Review			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Mercer SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
CNMP	15,432.9		
Filter Strips	153.4		
Conservation Cover	12.7		
Wetland Creation	5.5		
Tree/Shrub Establishment	2.0		
Windbreak/Shelterbelt Establishment - Acres	0.3		
Settling basin	0.1		
Drainage - Tile Main		26,257	
Grassed Waterway		22,932	
Subsurface Drain		10,113	
Technical Assistance - Drainage			41
Complaint Investigation/Resolution - Livestock			26
Underground Outlet			9
Grade Stabilization Structure			7
Drainage - I & E (Inventory & Evaluation)			7
Waste Storage Facility			1
Waste Transfer			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Miami SWCD

## 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Subsurface Drainage System	1.0		
Grassed Waterway		8,250	
Subsurface Drain		1,220	
Surface Drainage, Field Ditch		200	
Urban - I & E (Inventory and Evaluation)			36
APA - Site Visit			4



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Montgomery SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Subsurface Drain		1,432	
Grassed Waterway		1,430	
Pipeline		56	
CAUV Inspection			79
I & E (Inventory and Evaluation)			74
DM - Annual Maintenance Completed			22
Conservation Easement Inspection			12
Agricultural Easement Inspection			3
Stone Center Outlet			2
Stream Crossing			2
Technical Assistance - Drainage			1
Erosion - I & E (Inventory & Evaluation)			1
Watering Facility			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Preble SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Grassed Waterway		33,329	
Subsurface Drain		30,844	
Stone Center Outlet			24
Grade Stabilization Structure			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Shelby SWCD 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Subsurface Drain		23,295	
Grassed Waterway		21,261	
Grade Stabilization Structure			3



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Union SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Subsurface Drain		296,330	
Grassed Waterway		10,160	
Pond Site Investigation			3
Urban - Survey & Design			1
I & E (Inventory and Evaluation)			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Warren SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Cover and Green Manure Crop	1,246.8		
Soils Suitability Report	12.0		
Storm Drain Stenciling			1,687
Urban - Site Inspection			845
Urban - Detention Basin Inspection			541
Technical Assistance - Drainage			209
Pond Management			57
Urban - Plan Review			40
Technical Assistance - Streams			25
Soils - General Assistance			23
I & E (Inventory and Evaluation)			18
Technical Assistance - General			17
Technical Assistance - Oil & Gas			6
Erosion - I & E (Inventory & Evaluation)			5
Water Quality Sampling			4
Pond Site Investigation			3
Wetland Review			2
Urban - Illicit Discharge Investigation/Resolution			2
Technical Assistance - Silviculture			2
Erosion Control Structure			2
Stormwater Outfall Located			1
Conservation Easement Inspection			1
Sludge Application Assistance			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*