



# Adams SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
THP (Timber Harvest Plan) Review	199.0		
Cover and Green Manure Crop	88.3		
HEL Determination	48.5		
Heavy Use Area Protection	2.0		
Wetland Creation	0.6		
Fence		7,945	
Access Road		1,705	
Wildlife Damage Permit Issued - Deer			135
Beehive Inspection			20
Wildlife Damage Investigation - Deer			17
Agricultural Easement Inspection			10
Nuisance Animal Complaint			8
Technical Assistance - Streams			4
Technical Assistance - General			4
Pond Management			3
Spring Development			2
Watering Facility			2
Pond Site Investigation			2
Wildlife Damage - Other Species			2
CRP - MCM Assessment/Review			1
Technical Assistance - Drainage			1
Soils - General Assistance			1
Complaint Investigation/Resolution - Sediment			1
Wildlife Habitat Assistance			1
Wildlife Damage - Raccoon			1
Technical Assistance - Silviculture			1
Wildlife Assistance			1
Wildlife Damage Investigation - Canada Goose			1
Practice Inspection / Follow-up			1
Wildlife Damage - Coyote			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Athens SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
THP (Timber Harvest Plan) Review	350.0		
Equipment Rental - No-till Drill	132.8		
CNMP	25.0		
Equipment Rental - Seeder	14.2		
Brush Management	8.0		
Heavy Use Area Protection	1.0		
Subsurface Drain		800	
Urban - Site Inspection			58
Urban - Plan Review			42
Pond Site Investigation			7
Technical Assistance - General			5
Equipment Rental - Lime Spreader (Instance)			4
Pond Management			4
Natural Resource Review			3
I & E (Inventory and Evaluation)			3
Watering Facility			1
Technical Assistance - Drainage			1
Stormwater Outfall Located			1
Soils - General Assistance			



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Brown SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
CNMP	39.0		
Fence		6,758	
Grassed Waterway		2,060	
Wildlife Damage Permit Issued - Deer			231
Wildlife Damage Investigation - Deer			26
Urban - Subdivision Site Inspection			18
Technical Assistance - Drainage			9
Agricultural Easement Inspection			4
I & E (Inventory and Evaluation)			1
Pond Management			1
Nuisance Animal Complaint			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Delaware SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Cover and Green Manure Crop	2,224.8		
Agricultural Easement Installation	118.6		
Conservation Easement Installation	4.6		
Grassed Waterway		4,970	
CAUV Inspection			5,501
DM - Inspections			434
I & E (Inventory and Evaluation)			179
Conservation Easement Inspection			42
Urban - Subdivision Site Inspection			35
Equipment Rental - Other			20
Practice Inspection / Follow-up			13
Tile Plan Developed			11
Agricultural Easement Inspection			4
Seasonal High Tunnel System for Crops			2
Stream Crossing			1
Watering Facility			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Fairfiled SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Subsurface Drainage System	40,426.8		
Heavy Use Area Protection	0.1		
Grassed Waterway		6,342	
Surface Drainage, Main or Lateral		5,918	
Urban - Sediment & Erosion Control Inspection			566
Technical Assistance - General			456
Urban - Technical Visit			326
Urban - I & E (Inventory and Evaluation)			324
Wildlife Damage Permit Issued - Deer			248
Urban - Subdivision Site Inspection			68
Wildlife Damage Investigation - Deer			44
Urban - Subdivision Plan Review			44
Urban - Ind. Lot SWPPPs Approved			40
Wildlife Habitat Assistance			6
Wildlife Damage - Other Species			2
Pumping Plant			1
Grade Stabilization Structure			1
Stream Crossing			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Franklin SWCD 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Stream Restoration/Enhancement		70	
Urban - Site Inspection			831
Technical Assistance - General			13
Natural Resource Review			7
Urban - Plan Review			3
Urban - Technical Visit			3
Urban - Post Construction - Site Inspection			2
Urban - Rain Garden			2



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Gallia SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Prescribed Grazing	237.2		
Critical Area Planting	3.3		
Mulching	3.3		
Heavy Use Area Protection	0.2		
Fence		31,158	
Pipeline		2,754	
Access Road		775	
Flood Plain Permit Issued			25
Technical Assistance - Silviculture			5
Watering Facility			4
I & E (Inventory and Evaluation)			2
Spring Development			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Highland SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Cover and Green Manure Crop	716.0		
Pasture and Hayland Planting	127.4		
Heavy Use Area Protection	1.0		
Fence		18,488	
Subsurface Drain		11,646	
Grassed Waterway		11,503	
Pipeline		5,310	
Access Road		552	
Lined Waterway or Outlet		80	
Urban - Sediment & Erosion Control Inspection			21
Watering Facility			7
Spring Development			1




*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Hocking SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
THP (Timber Harvest Plan) Review	310.0		
Brush Management	116.0		
Forest Stand Improvement	52.0		
Prescribed Grazing	20.0		
Tree/Shrub Establishment	6.0		
Pipeline		547	
Underground Outlet			290
Roof Runoff Structure			154
Wildlife Damage Permit Issued - Deer			23
Technical Assistance - General			22
Technical Assistance - Silviculture			14
Pond Management			12
NOI (Timber Harvest) Submitted			6
Wildlife Habitat Assistance			3
Technical Assistance - Drainage			3
Practice Inspection / Follow-up			2
Site Meeting / Review			2
Wildlife Damage Investigation - Deer			1
Wildlife Assistance			1
Technical Assistance - Streams			1
Erosion - I & E (Inventory & Evaluation)			1
Wetland Review			1
Watering Facility			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Jackson SWCD

## 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Tree/Shrub Establishment	7.0		
Fence		2,000	
Grassed Waterway		630	
Wildlife Damage Permit Issued - Deer			1
Site Meeting / Review			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Lawrence SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Equipment Rental - No-till Planter	413.7		
Equipment Rental - Lime Spreader (Acres)	386.0		
Equipment Rental - No-till Drill	307.6		
Equipment Rental - Fertilizer Spreader	5.0		
Heavy Use Area Protection	0.1		
Fence		15,155	
Access Road		4,378	
Pipeline		325	
Flood Plain Determination			197
Flood Plain Permit Issued			155
Floodplain Project Inspections			132
Urban - Subdivision Site Inspection			22
Floodplain Site Investigations			22
Urban - Sediment & Erosion Control Inspection			19
Urban - Site Inspection			6
Urban - SWPPP Approved			4
Urban - Plan Review			3
Spring Development			2
Watering Facility			2



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Meigs SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Pasture and Hayland Planting	68.0		
THP (Timber Harvest Plan) Review	60.0		
Irrigation System - Microirrigation	0.4		
Heavy use protection pad constructed with stone and geo-textile fabric	0.2		
Fence		18,829	
Pipeline		1,890	
Subsurface Drain		352	
Wildlife Damage Investigation - Deer			12
Wildlife Damage Permit Issued - Deer			12
Watering Facility			5
NOI (Timber Harvest) Submitted			4
Stream Crossing (Timber Harvest)			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Pickaway SWCD 2014 Technical Summary



<b>BMP Type / Service</b>	<b>Total Acres</b>	<b>Total Feet Installed</b>	<b>Instance(s) of Assistance Provided</b>
Subsurface Drain		494,456	
Grassed Waterway		38,139	
Blind Inlet			18
Stone Center Outlet			11
Grade Stabilization Structure			3



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Pike SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
THP (Timber Harvest Plan) Review	1,013.0		
Equipment Rental - No-till Drill	400.6		
Soils Suitability Report	106.0		
Rural - Property Evaluation	53.0		
Cover and Green Manure Crop	9.3		
Heavy Use Area Protection	0.1		
Pipeline		780	
Access Road		687	
Soils - General Assistance			8
Technical Assistance - Streams			4
Erosion - I & E (Inventory & Evaluation)			4
Pond Site Investigation			3
Technical Assistance - Drainage			2
Pond Management			2
Watering Facility			1
Practice Inspection / Follow-up			1
Technical Assistance - General			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Ross SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Equipment Rental - No-till Drill	899.0		
Equipment Rental - Seeder	40.0		
Subsurface Drain		2,800	
Fence		2,015	
Grassed Waterway		1,400	
NOI (Timber Harvest) Submitted			2
Grade Stabilization Structure			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Scioto SWCD 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
THP (Timber Harvest Plan) Review	1,211.0		
Farmland Preservation	999.8		
Brush Management	36.0		
Forest Stand Improvement	29.0		
Cover and Green Manure Crop	28.4		
Irrigation System - Microirrigation	5.6		
Heavy Use Area Protection	0.4		
Critical Area Planting	0.3		
Mulching	0.3		
Fence		4,622	
Pipeline		1,835	
Access Road		785	
Wildlife Damage Permit Issued - Deer			304
Wildlife Damage Investigation - Deer			38
CRP - MCM Assessment/Review			13
I & E (Inventory and Evaluation)			10
Watering Facility			3
Pond Site Investigation			3
Soils - General Assistance			2
Underground Outlet			1
Roof Runoff Structure			1
Erosion - I & E (Inventory & Evaluation)			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*



# Vinton SWCD

## 2014 Technical Summary



BMP Type / Service	Total Acres	Total Feet Installed	Instance(s) of Assistance Provided
Woodland - Management Plan Developed	1,009.5		
Woodland - Management Plan Inspection	324.0		
Timber Cruising / Marking	206.8		
THP (Timber Harvest Plan) Review	148.0		
Tree Farm Re-Inspection	55.0		
Forest Stand Improvement	52.0		
Brush Management	45.0		
Forest Trails and Landings		300	
Wildlife Habitat Assistance			15
CAUV Inspection			11
Wildlife Damage Permit Issued - Deer			10
Technical Assistance - Silviculture			9
CRP - MCM Assessment/Review			5
Wildlife Damage Investigation - Deer			4
Pond Management			4
I & E (Inventory and Evaluation)			3
Nuisance Animal Complaint			2
Site Meeting / Review			2
Soils - General Assistance			1
Stream Crossing			1
Pond Site Investigation			1
Wildlife Damage - Beaver			1



*Data derived from ODNR Division of Soil and Water Resources  
Soil and Water Information Management System (SWIMS)*