


HORIZONTAL MARCELLUS WELL ACTIVITY IN OHIO



EXPLANATION

Horizontal well status as of 6/4/2022

- ◆ PERMITTED-(Permitted; Not Drilled; Canceled) (20)
- DRILLED-(Drilling; Well Drilled) (10)
- PRODUCING-(Producing; Plugged Back) (44)
- INACTIVE-(Drilled Inactive; Shut in) (2)
- Lost Hole or Final Restoration (1)

OPERATOR	COUNT
ASCENT RESOURCES UTICA LLC	3
CNX GAS COMPANY LLC	1
DIVERSIFIED PRODUCTION LLC	1
EAP OHIO LLC	1
ECLIPSE RESOURCES I LP	3
EM ENERGY OHIO LLC	1
EQUINOR USA ONSHORE PROPERTIES INC.	15
HESS OHIO RESOURCES LLC	3
PHILLIPS EXPLORATION INC	1
PROTEGE ENERGY II LLC	1
SWN Production (Ohio) LLC	34
TRIAD HUNTER LLC	8
XTO ENERGY INC.	5
TOTAL	77

Well permit information from the ODNR Division of Oil and Gas Resources Management

Recommended citation:

Ohio Department of Natural Resources, 2022, Horizontal Marcellus Well Activity in Ohio: Columbus, scale 1:1,300,000, revised 7/11/2022.

